



splices between brickwork and tray to be filled with mineral wool and sealed

existing brickwork

The transfer tray is inserted top-down into the prepared opening or slid in from cashier side.  
The movement gear is mechanical.

To avoid overload of the coverframe, the transfer tray has to be supported by a 3rd-party sub-construction, e.g. steel pipes!

This device is manufactured with highest accuracy. Anyway, repairs could become necessary after a long-term use. For this purpose, the disassembling of the above positioned glass should be possible, or the option to pull out the device from customer side.

Subject to modifications.

### EI30 Counter Top Transaction Tray

**Part Numbers**  
**EI30/590/640 JB 9005**  
**EI30/590/640 SS**

REV	DESCRIPTION	DATE
REVISIONS		
	DWG. NO: .	
	TITLE:	
	EI30 Counter Top Transaction Tray	
<small>FOR ILLUSTRATIVE PURPOSES ONLY. DO NOT SCALE FROM THIS DRAWING. ALL DIMENSIONS TO BE VERIFIED ON SITE. UNLESS OTHERWISE SPECIFIED, DIMENSIONS ARE IN MM.</small> <small>THIS DRAWING/SPECIFICATION REMAINS THE COPYRIGHT OF ARCHITECTURAL ARMOUR AND MUST NOT BE COPIED IN ANY FORM WHATSOEVER WITHOUT PRIOR WRITTEN PERMISSION.</small>		



**Architectural Armour**

+44(0)1981 257000 sales@architecturalarmour.com  
 www.architecturalarmour.com

4 The Courtyard, Station Rd, Dullingham. CB9 9UP. UK

DRAWN .  
 APPV'D .  
 SCALE 1:10@A4  
 WEIGHT .

INITIALS

DWG. NO: .  
 TITLE:  
 EI30 Counter Top Transaction Tray